

NYISO-PJM JOA Update

Simon Tam
Operating Committee
January 12, 2023

www.pjm.com | Public PJM © 2023



- PJM and NYISO have their own respective procedures in determining Interconnection Reliability Operating Limits (IROLs)
- The PJM-NY Interface was considered as IROL by NYISO but not by PJM
- A recent joint study* by PJM and NYISO concluded the PJM-NY Interface does not meet the IROL criteria of NYISO. NYISO has decided to remove the PJM-NY Interface as being an IROL.

^{*} The joint study report is available at https://www.nyiso.com/documents/20142/3694023/NP-22-NY-PJM-JointStabilityAnalysis-Approved-OC-10-13-2022.pdf/3b35120a-3e5b-eb6e-d704-946f7df57ce1



The NYISO-PJM Joint Operating Agreement (JOA) is being updated to reflect the recent NYISO change.

35.5.9 New York - PJM IROL Interface(s)

The Parties share a joint IROL related transfers related to the interconnecting transmission lines between their respective Reliability Coordinator Areas and Balancing Authority Areas. This IROL is adhered to will adhere to IROLs that each Party develops in accordance with its respective procedures. in order IROLs will be determined as needed to maintain acceptable steady-state and transient performance of the NYISO and PJM Transmission Systems. Each Party will specify the list of IROL Interfaces in its procedures. Both Parties will monitor this limit these limits in accordance with this Agreement and independently determine the applicable import and export transfer limits.



Presenter:

Simon Tam, simon.tam@pjm.com

NYISO-PJM JOA Update



Member Hotline

(610) 666 - 8980

(866) 400 - 8980

custsvc@pjm.com

