



M-36 System Restoration Update

Glen Boyle
Reliability Standards and Compliance Subcommittee
April 21, 2017



- Annual Update
 - Cover to cover review
 - Minor grammatical changes and clarifications throughout
- Changed “Generation Owner/MOC dispatcher” to “Generator Operator” throughout manual to match NERC Standard EOP-005 terminology
- Section 1.1
 - Removed references to EOP-009 and EOP-007-RFC-1 as these standards have been retired
- Section 7.1.2
 - Removed Exhibit 10 (Locations of Synchronization Devices) due to this information being in TO restoration plans

- Section 8.1 – Restoration Plan Guidelines
 - Added template for generation information to be included in TO Restoration Plans
- Attachment A – Minimum Critical Black Start Requirement - Removed references to System Restoration Strategy Sr. Task Force as this group has been sunset
- Attachment B – updated email address on restoration forms
- Attachment D – Restoration Drill Guide – changed participation requirement for Generator Operators from Fall drills to Spring drill

- Attachment F – Annual update of table in Figure 1 referencing TO restoration plans
- Attachment G – Coordination of Restoration Plan Updates
 - Added detail to section G-4 on process for TO update of restoration plans for planned BES modifications
 - Updated dates for First Energy, ITCI and RECO annual restoration plan update



Manual Review Schedule

- SOS
 - First Read 4/5/17
 - Endorsement 4/26/17
- OC
 - First Read 4/11/17
 - Endorsement 5/2/17
- MRC
 - First Read 4/27/17
 - Endorsement 5/25/17

Manual Effective Date – June 9, 2017