

<b>Effective Date</b>	12/1/2015
<b>Impacted Manual #(s)/Manual Title(s):</b>	
Manual 12: Balancing Operations	
<b>Conforming Order(s):</b>	
<b>Associated Issue Tracking Title:</b>	
<b>Committee Approval Path - What committee(s) have already seen these changes?</b>	
SOS, OC, MRC	
<b>MRC 1<sup>st</sup> read date:</b>	10/22/15
<b>MRC voting date:</b>	11/19/15
<b>Impacted Manual sections:</b>	
<ul style="list-style-type: none"> <li>• Section 3.2, Section 4 and Attachment A</li> </ul>	
<b>Reason for change:</b>	
Periodic review, updates due to new IRC implementation	
<b>Summary of the changes:</b>	
<ul style="list-style-type: none"> <li>• Section 3.2 updated to eliminate mention of Midwest ISO as the Interconnection Time Monitor.</li> <li>• Section 4 <ul style="list-style-type: none"> <li>○ Instances of ‘Supplemental Reserve’ replaced with ‘Secondary Reserve’.</li> <li>○ Instances of ‘Quick start reserves’ replaced with ‘Quick-Start Reserves’ to match definition in Manual 35.</li> <li>○ Section 4.1.1: <ul style="list-style-type: none"> <li>▪ Values updated to match new IRC values.</li> <li>▪ Reference to unit level reporting added.</li> </ul> </li> </ul> </li> <li>• Attachment A exhibits (17, 18, 19) updated to be consistent with terms and screenshots used in the new IRC (Instantaneous Reserve Check).</li> </ul>	