



2016 Summer Emergency Procedures Drill Debrief

May 10, 2016

Applications

1. A few companies were unable to view data they submitted in the SSR form. These companies might have been looking in the wrong area of the SSR under the History button.
2. Several transmission owners could not access the SSR; this is by design as all load management information is sent to eLRS application by Curtailment Service Providers.
3. The Emergency Procedures posting message for Emergency Voluntary Energy Only Demand Response had a required field for lead time and product type. There is no lead time or product type for this form of Demand Response. This issue has been corrected.
4. One company reported intermittent loss of the Emergency Procedure posting application. PJM did follow up with this company and awaiting a response.
5. PJM also has a Markets & Operations section of the pjm.com webpage that was incorrectly putting out all drill messages but not stating "Drill" anywhere in the message. This section of the webpage was shut down by PJM shortly after being discovered during the Drill. This discrepancy has been corrected and future Drill messages will not be posted in the future.

Satellite Phone

1. Satellite phones will not be used for future drills because some companies participate in the drill from a location that doesn't have satellite phones available.

All-Call

1. One company requested slowing down message and annunciating better for critical messages. This comment was specifically directed to all call issuing load shed amounts.

Training/Manuals

1. ACES Power did not receive any Debrief Log Sheet or a Drill Information Package.
2. PBF Energy/PBF Power Marketing was unaware of the drill. PJM contacted PBF and notified them to contact their SOS or DTS representative.
3. Several companies were able to identify areas in their internal procedures, all calls, and manuals that need to be updated to reflect changes in PJM procedures.
4. The new emergency procedure to Deploy All Resources Action was not in M-13 prior to the drill and several companies noted that they were unclear on company



2016 Summer Emergency Procedures Drill Debrief

May 10, 2016

actions for this procedure. The procedure is being finalized through the Committee process and will be posted after approval at the MRC on 5/26/16.

General

1. Multiple SOS-T companies were calling into the Corporate Communicators 0930 call using the number from the 0900 SOS-T call. The wording of the drill information sent out to members will be changed to avoid this in future drills.
2. There was an issue when PJM requested Manual Load Dump and CPP were not specifically identified to dump load. CPP was contacted and will look to get clarification through SOS.
3. Several companies sent in their operator logs for the drill debrief. The operator logs were basically just a list of all emergency procedures issued and the times they were issued. Please note that this is not necessary to send. Just note any problems encountered, state what worked well, or changes you feel need to be made for the drill.
4. One company sent in screen shots from PJM Emergency Procedures Posting application of all emergency procedures issued.

Drill Highlights

1. **Successful use of Send Word Now notification application.**

For questions or comments, please contact the PJM Emergency Procedures Drill Coordinators:

Bill Powell and Dave Turtle,
epdrill@pjm.com
Phone: 610-955-2466

Other Contacts:

General Issues: PJM Help Desk 610-666-4500

Satellite Phone Issues: engtechs@pjm.com

Member Training Issues: membertrainingdept@pjm.com

CEH Submission: trainingsupport@pjm.com