



Executive Summary Manual Changes

Effective Date	6/15/2021
Impacted Manual #(s)/Manual Title(s):	
PJM Manual 36: System Restoration	
Conforming Order(s):	
Associated Issue Tracking Title:	
Committee Approval Path - What committee(s) have already seen these changes?	
<p>First Reads:</p> <ul style="list-style-type: none"> • SOS: April 5, 2021 • OC: April 8, 2021 • MRC: April 28 <p>Second Reads:</p> <ul style="list-style-type: none"> • SOS: May 10, 2021 • OC: May 14, 2021 (endorsement) <p>MRC Endorsement:</p> <ul style="list-style-type: none"> • May 26, 2021 	
MRC 1st read date:	4/21/2021
MRC voting date:	5/26/2021
Impacted Manual sections:	
Attachments B, F, G, and H	
Reason for change:	
Annual update requirement.	
Summary of the changes:	
<ul style="list-style-type: none"> • Annual Update Cover to cover review. • Attachment B Exhibit 16: Replaced with a clearer image • Attachment F: Removed information; Linden and Neptune restoration plans are in eDART. • Attachment G: Updated Table 1, Annual Restoration Plan Review Deadlines, with current list of Transmission Owners. 	

- **Attachment H:** Updated Under Frequency Load Shed table with new data and noted PJM's UFLS program does not require automatic switching of Capacitor banks, Transmission Lines, or reactors (PRC-006 R10).