

Dominion Virginia Electric Power (DOM)

1. **Ladysmith #2 500/230 kV Transformer Sectionalized** – Restores the 500 kV Bus Breakers for a fault on the Ladysmith #2 500/230 kV transformer.
 - Effective November 23rd, 2021

Pennsylvania Power & Light Company (PPL)

1. **West Hempfield #3 230/138 kV Transformer** – Restores the 230 kV High Side CBs following a fault on the transformer.
 - Removed August 30th, 2021